


## LIONEL SERVICE MANUAL





Note how the electromagnet coil leads are soldered to the ground rail and to the metal yoke joining the two left-hand control rails to the second controller conductor. The ground coil lead must be insulated from the metal coil bracket which is normally at track voltage potential.



CONTROL RAIL
GROUND

CONTROL R

PRINTED IN U. S. OF AMERICA
(Replaces Page 3, STC-RCS, Dated 11-48)